



BUREAU
VERITAS

Bureau Veritas Certification

Certification

awarded to

Boskalis Environmental B.V.

Rosmolenweg 20, 3356 LK Papendrecht, The Netherlands

Bureau Veritas Inspection and Certification The Netherlands B.V. declares that the Safety, Health and Environmental Management System of the above organisation has been audited and found to be in accordance with the requirements of the standard detailed below.

Standards

SCC** 2017/6.0

Scope of supply

- soil and sediment remediation (all project locations);
 - processing and cleaning of contaminated soil, dredged sediments and other mineral wastes (at location GBD Alkmaar);
 - production of secondary raw bulk and mineral materials (at location GBD Alkmaar)
- NACE Code: E.39.00

Original cycle start date: **26 March 1995**

Expiry date of previous cycle: **1 July 2021**

Certification / Recertification audit date: **20 May 2020**

Certification / Recertification cycle start date: **11 March 2021**

Subject to the continued satisfactory operation of the organisation's Management System, this certificate is valid until: **12 March 2024**

Certificate No: **NL022616/110** Version: **1** Revision date: **11 March 2021**

Anton Kerbusch – Director Certification Benelux

Certification body address: Bureau Veritas Inspection and Certification The Netherlands B.V
Computerweg 2, 3821 AB Amersfoort
Local Office: Bureau Veritas Inspection and Certification The Netherlands B.V Computerweg 2, 3821 AB Amersfoort

Further clarifications regarding the scope and validity of this certificate, and the applicability of the management system requirements, please call: + 31 (0)88 450 5500





BUREAU
VERITAS

Bureau Veritas Certification

Appendix
awarded to

Boskalis Environmental B.V.

Rosmolenweg 20, 3356 LK Papendrecht, The Netherlands

Certificate No.: NL022616/110

The certificate also concerns below mentioned organisation(s) and site(s):

Standard

SCC 2017/6.0**

Scope of supply

Site	Address	Scope
Boskalis Environmental B.V.	Rosmolenweg 20, 3356 LK Papendrecht, The Netherlands	Soil and sediment remediation (all project locations)
GBD Alkmaar	Boekelerdijk 13, 1812 LV Alkmaar, The Netherlands	Processing and cleaning of contaminated soil, dredged sediments and other mineral wastes. Production of secondary raw bulk and mineral materials.

Revision date: **11 March 2021**

Anton Kerbusch – Director Certification Benelux

Certification body address: Bureau Veritas Inspection and Certification The Netherlands B.V.

Computerweg 2, 3821 AB Amersfoort

Local Office: Bureau Veritas Inspection and Certification The Netherlands B.V. Computerweg 2, 3821 AB Amersfoort

Further clarifications regarding the scope and validity of this certificate, and the applicability of the management system requirements, please call: + 31 (0)88 450 5500

vca^v


MGMT. SYS.
RVA C 248